

Resetting adaptation

XC90, 2008, B6324S, TF-80SC AWD, YV4CZ982081451588, 451588

15/1/2015



PRINT

Resetting adaptation

Resetting adaptation
Resetting the adaptation and the counter for "Transmission oil, replace"

Hint: The transmission has torque-regulated, adaptive pressure regulation. The pressure regulator enables the transmission to regulate pressure during each shift to prevent hard shifting. Each shift is assessed by the transmission control module (TCM) and is stored in the internal memory. This makes it possible to compensate for transmission and clutch wear. It is important that the adaptation in the memory is reset so that the transmission works normally after the repair. Because the fluid was changed during the repair, the counter for transmission fluid change must also be reset. If the counter is not reset during draining/replacement, a diagnostic trouble code may be generated under the wrong conditions.

Note! This applies only if the

transmission or one of the components in the transmission have been replaced.

- Ignition on.

Click on the VCT2000 symbol to reset the adaptation and counter.

15/ 1/ 2015

PRINT