

Resetting the service reminder indicator (SRI), model years 2002-

The service reminder indicator (SRI) informs the driver that it is time for the car to be serviced. The text message is displayed for 120 s each time the ignition is switched on.

Proceed as follows to reset the service reminder indicator (SRI):

- Ignition position I
- Press and hold in the reset button for the trip odometer
- Ignition position II.

Note! Turn the key to position II within 2 seconds.

- Hold the reset button for the trip meter pressed in until the original value has been reset.

Note! For all vehicles from the 2003 model year a general yellow lamp will light when the reset button must be released.

- Release the reset button for the trip odometer within 4 seconds. The instrument gives an audible signal when resetting has succeeded
- If the trip meter is already reset the reset button should be held in for a minimum of 10 seconds and a maximum of 14 seconds.

Note! If the reset button for the trip odometer is not released within 4 seconds, the service reminder indicator (SRI) is not reset.