

DETAILS


NETWORK

FAULT TRACE

REFERENCE INFORMATION

VEHICLE COMMUNICATION





Engine control module (ECM)

Connected

 10.8 V

 Pos II

Initial State

Selected CSC

Unselected CSC

Delivery

 Driving, Hesitates/surges, At steady speed, BV 

 UPDATE

ACTION HISTORY

  ECM-913C Throttle valve - Faulty signal

  ECM-919A Engine control module (ECM) - Faulty signal

  ECM-91A7 Throttle valve - Faulty signal

  ECM-91B7 Throttle valve - Faulty signal

  ECM-9150 Throttle unit, potentiometer 1 - Faulty signal

  ECM-9160 Throttle unit, potentiometer 2 - Signal too low

  ECM-9170 Throttle valve - Faulty signal

 Checking compression

 Checking for knocking and rasping

 Checking fuel and residual pressures

 Checking injectors

 Checking spark plugs

 Checking the freewheel on a generator (GEN)

 Checking three-way catalytic converter (TWC) and exhaust system

 VIEW INF

 DETAILS

 TIMELINE