

370,1999,B5234T3,YV1LS53D5X2577604

Delivery 1/15/2014 5:34:49 PM

Control Module - Diagnostic Trouble Code	Status
ABS-0095 Control module communication Control module communication	DTC is found active.
ABS-0093 Control module communication Control module communication	DTC is found active.
CCM-414 Fan motor passenger compartment temperature sensor Faulty signal	DTC is found active.
CDM-0001 Vehicle speed signal (VSS) Signal missing	DTC is found not active.
CDM-000D Communication, ECM Internal fault	DTC is found not active.
CDM-E000 Control module communication	DTC is found not active.
ECM-4050 Fuel level sensor - Signal missing	DTC is found not active.
ECM-510F Vehicle speed signal (VSS) - Signal missing	DTC is found not active.
ECM-530B Malfunction indicator lamp (MIL) communication -	DTC is found not active.
ECM-902A Communication with throttle unit - Signal too low	DTC is found not active.
ECM-903F Throttle position (TP) - Signal too low	DTC is found not active.
ECM-E003 Configuration fault - Software fault	DTC is found not active.
ETM	No fault found
IMM	No fault found
SRS	No fault found
TCM	No fault found
VGLA	No fault found