

XC90, 2007, B6324S, TF-80SC AWD, R.H.D

30/12/2017



PRINT


Operation number:
25102-2


Induction pipe

Note! Some variation in the illustrations may occur, but the essential information is always correct.

Removal



Note! Removal steps in this procedure may contain installation details.






M6.

Refer to: Tightening torque



M7.

Refer to: Tightening torque



Installation

To install, reverse the removal procedure

30/12/2017

PRINT