

2013 Volvo XC70 T6 Flamenco Red YV4902BZ4D1147885

PM / Repair	mileage	date	comment
purchased	104,178	10/13/18	Ken Garff Volvo, SLC Utah
new windshield, camera calibr.			
new tires			
4-wheel alignment			
oil & filter			
mech. recondition kit			
27 point inspection			
water pump replaced			Ken Garff Volvo, SLC Utah
new air filter + enclosure box	104,944	10/16/18	small crack seen in box lid
CA Smog Test	104,972	10/20/18	pass
new battery	106,000	11/17/18	Interstate MT-92 T7
pollen filter	107,000	1/22/19	
transmission flush	108,000	4/2/19	brown, no burnt smell
AWD service			
angle gear oil	108,500	4/17/19	good color, no metal chaff
Haldex AOC fluid			good color, no metal chaff
rear axle diff oil			good color, no metal chaff
radiator surface decratered	108,800	4/25/19	coolant 99C before, 88C after
fuel tank shroud	108,900		plastic shroud replaced, alum. shield bent straight
			park-assist feature intentionally disabled
PCV oil trap replaced	109,254	5/14/19	membrane broke, made chirping sound, Big O
oil & filter	110,200	7/10/19	new splash shield anchors
spark plugs	110,350	7/17/19	looked barely used, ign. wire sheathing cracked/repared in 2 places
Volvo Cars Walnut Creek	110,800	7/31/19	
multi-point inspection			no problems reported
reset transmission counter			
stereo volume too low at startup (was there a software fix? they don't know)			
oil & filter	115,200	6/9/20	vacuum method, LiquiMoly 10W-40 anti-friction
rotate tires F<->R	115,700	6/20/20	wheel bearings and steering linkage tight
new air filter	116,200	7/1/20	Volvo
power steering flush	116,300	7/9/20	per VolvoSweden YouTube
refueling problem	117,200	9/19/20	unclogged Refueling Vent Pipe Filter
oil & filter	117,800	10/28/20	Liqui-Moly 5W-30 Special Tec LL
replace coil packs	117,820	10/29/20	Volvo brand
Volvo Cars Walnut Creek	118,600	1/27/21	
multi-point inspection			no problems reported
Park Assist syst needs serv			tech thinks it will need new PAM electronic module
replace door harness tie-wrap			
fix USB port in console box			
brake fluid flush	120,000		
oil & filter	125,000		Liqui-Moly 5W-30 Special Tec B FE
new tires + TPMS sensors	125,000		
coolant flush	130,000		
new air filter	126,000		
fix fuel level sender			this cannot be done bc it's part of the fuel tank
Accessory belt replacement	150000		remove front bumper, replace PAM