



The CEM is a different design starting in 2005 so you need to also consider the primary connector(54/4LA-G) and signals between the CEM, BCM, ECM and TCM modules. 54/3 (2002 wiring diagram shown). Have you compared the pinout and wiring of this connector between model years? This is the connector where the engine harness connects to the passenger compartment harness (CEM).



Cable harness routing in vehicle
Front engine compartment harness LHD



Cable harness routing in vehicle Front passenger compartment harness LHD

