

S60 (11-), 2012, B5254T5, TF-80SC, L.H.D





4/12/2023

PRINT


Operation number:
21813-2

Engine Pad right

Special tools	
	999 5716 LIFTING BEAM (ENGINES) USED WITH 2 X 999 5460 Tool number:999 5716 Tool description:LIFTING BEAM (ENGINES) USED WITH 2 X 999 5460 Tool boards:21
	999 7254 Hook Tool number:999 7254 Tool description:Hook Tool boards:21
	999 5460 Lifting hook Tool number:999 5460 Tool description:Lifting hook Tool boards:21

Removal

Note! Removal steps in this procedure may contain installation details.




Remove the upper torque rod

Refer to: Upper torque rod



Special Tool: 999 5716






Remove the screws.



Special Tool: 999 7254

Special Tool: 999 5460



Remove the following items:

1. **Torque:** M12, 80 Nm
2. **Torque:** Bracket engine mounting to cylinder head, 48 Nm
3. **Torque:** M12, 80 Nm

Torque: M12, 80 Nm

Installation

To install, reverse the removal procedure.

PRINT

4/12/2023