

873: Climate unit, B6304T2, L.H.D


S80 (07-), 2008, B6304T2, TF-80SC AWD, L.H.D



7/3/2014







PRINT

873: Climate unit, B6304T2, L.H.D**Operation number:**
87306-2**Blower motor
passenger
compartment**

Special tools	
	999 7284 Installation tools Tool number: 999 7284 Tool description: Installation tools Tool boards: 87



Removal**Note! Removal steps
in this procedure may
contain installation
details.**Remove the combined
instrument panelRefer to: Combined
instrument panel






Remove control module
relay box passenger
compartment

Refer to: Control
module relay box
passenger compartment







Torque: M8, 24 Nm

**Vehicles with air
quality sensor**




All vehicles



Caution! Take extra care when handling the component.

Special Tool: 999 7284




Caution! Take extra care when handling the component.

Installation

Caution! Make sure that the blower motor and fan assembly is placed on the bench with the fan pointing upwards.

Note! Replace with a screw if necessary.

If necessary



To install, reverse the removal procedure.

Perform climate unit, checking

Refer to: Climate control system, check

PRINT

7/3/2014