

882: Interior equipment

C70 (06-), 2009, B5254T7, AW55-50/51SN, L.H.D

18/11/2019

882: Interior equipment**PRINT****Operation number:**

88232-2

Center console

Note! Some variation in the illustrations may occur, but the essential information is always correct.

Removal

Note! Removal steps in this procedure may contain installation details.





Remove the following items:






- seat cushion






Refer to: Seat cushion, rear seat
- cup holder, floor console


Refer to: Floor Consol Cup holder












Remove the centre console screw underneath.

Refer to: Tightening torque



Remove the Climate control module (CMM) screw.

Refer to: Tightening torque



Installation

To install, reverse the removal procedure

18/11/2019

PRINT